

*Central Boat Rentals, Inc.*  
*"Barge Specialists"*

October 20, 2006

Mr. Morgan Turrell  
N.T.S.B.

RE: Position of engine transmission linkage on the M/V MISS MEGAN

Morgan:

As per our conversation on 10/19/06, the control cables leading to both transmissions are seized in the neutral position. It appears the cables going to the master control are melted and will not move. Please note photo files attached.

Respectfully,



Central Boat Rentals, Inc.  
Gary Gaudet  
Vice President Operations